FILE NOTATIONS	7
Entered in FTD File	Charled by Chief
Cocstion Hor Dinned	Approved Letter 2:13:73
Card Indexed	Elsapproval Letter
COMPLETION DAWN: Date Well Completed 4.24	Location Inspected
OW WW TA GW OS PA	Bond released State or Fee Land
	FILED
Driller's Leg	
The verice ( vio (do.)	
gor S. J Dat I Lit	GR-N Micro
v. 2 ( <b>%:10 So</b> nio Ch. P.,, Jach.,	Ma-L Senic
Chlog Culog Út	

February 4, 1975

Mr. Ed Guynn
U.S.G.S. Acting District Engineer
8th Floor, Federal Building
Salt Lake City, Utah 84111

Dear Sir:

C.C. Co. of Salt Lake City, Utah wishes to make application to drill a test well on Lease # U 16965 A in Section 11 T 21, So. R 23 E, Grand County, Utah as filed in triplicate on form 9-331C.

In addition to the information given on form 9-331C, may we submit the following information on a 12 point plan of development:

- 1. Existing roads. Attached is a photo copy of U.S.G.S. quadrangle showing main highways and access roads leading to well location in Section 11, T 21 S, R 23 E.
- 2. Planned access roads. The C.C. Co. Adak # 11-1 will be 1/4 mile north of Interstate 70 and can be reached from existing roads which service the Vukasovich and Lansdale gas wells in Sections 2, 3, and 10. A graded access road 1/8 mile long connects with the old dirt road north from Cisco to Promatory wells in Section 2, T 21 S, R 23 E. The leasee agrees to upgrade the road to the well or other improvements which may be required by the B.L.M. District Manager or his authorized representative. In the event the well becomes a producer, leasee agrees to upgrade existing roads which may include culverts, graveling and secondary improvements.
- 3. Location of wells. The proposed location of C.C. Co.-Adak #11-1 is one mile east of the Losey gas well in Section 10, two miles southeast of the Vukasovich Fed. #5 well and one mile south of east from the Grand Gas Pipeline.
- 4. Lateral roads to well location. (See attached map).
- 5. Location of tank batteries and flow lines will be set after drilling rig is removed and location graded. Flow lines will be laid in best location for connection to existing gas trunk line.

Ed Guynn C.C. Co. - Adak 11-1

- 6. Location and types of water. Water can be hauled from the Colorado River 7 miles to the southeast. Test well will be drilled with air and air mist.
- 7. Waste disposal. Liquid wastes will be temporarily run in reserve pit--solids to the refuse pit and removed after drilling.
- 8. Location of camp. No camp required.
- 9. Location of airstrip. No airstrip required.
- 10. Rig location layout. (See rig layout sheet.)
- 11. Restoration of surface. When drilling is completed and equipment removed, surface will be graded and restored in accordance with the B.L.M. program for well site restoration. A gravel base will be set for tanks and driveways to production facilities.
- 12. Broadhead Drilling Co./will be equipped with A.P.I. Series 600 Double Ram Blowout Preventors. Tests will be made before drilling out from under surface, checked daily and when drill comes out of hole.

C.C. Co. trusts that the above drilling proposal, with map, charts and forms, will provide necessary information to grant permit to drill the C.C. Co. - Adak #11-1 well.

Very truly yours,

Lewis F. Wells, Agent

C. C. Co.

LFW/hw

Encl.

	DEFARTMEN		LICIOIN	5. LEASE DES	iunation and seeial no.
	GEOLO	GICAL SURVEY		U 169	65 A
APPLICATION	Y FOR PERMIT	O DRILL, DEE	PEN, OR PLUG B	ACK 6. IF INDIAN,	ALLOTTES OR TRIBE NAME
1a. TYPE OF WORK					
DRI	LL 🕱	DEEPEN 🗌	PLUG BAC	K T 7. UNIT AGRE	EMENT NAME
b. TYPE OF WELL			MULTIPE	8. PARM OR L	
	ELL X OTHER		ZONE ZONE		
2. NAME OF OPERATOR				Adak I	Base
C.C. Co.			·		N- 14 4
3. ADDRESS OF OPERATOR			NO. 11-1		
	me St. S.L.J.,		- 534-4		
At surface	eport location clearly and			Ciaco	
18901			th line, Sec. 11	11. SEC., T., R AND SURV	BY OR ARBA
At proposed prod. son	e T 21 S, R 23 Lame with		HE MUSE	Sec. 11, NE <del>1</del> , NW	T 21 S, R 23 E
14. DISTANCE IN MILES	AND DIRECTION FROM NEA	REST TOWN OR POST OF	FICE*		R PARISH 13. STATE
10 miles ear	st of Cisco,	Utah	•	Grand	Utah
16. DISTANCE FROM PROP LOCATION TO NEARES: PROPERTY OR LEASE I (Also to nearest drig	r 1840'		NO. OF ACRES IN LEASE	17. NO. OF ACRES ASSIGNATION TO THIS WELL 160	
18. DISTANCE FROM PROF TO NEAREST WELL, D OR APPLIED FOR, ON TH	RILLING, COMPLETED,	1 mile	1200 1	20. ROTARY OF CABLE TO ROTARY tool	
21. ELEVATIONS (Show wh	ether DF, RT, GR, etc.)			22. APPROX.	DATE WORE WILL START
	4450' GR			March	1. 1975
23.	I	PROPOSED CASING A	ND CEMENTING PROGRA	м	
SINE OF HOLE	RIZE OF CARING	WEIGHT PER FOOT	SETTING DEPTH	QUANTITY	of Cement
9"	7"	used 10.5	90' (3 joints	) Cemented ba	ck to surface
63.11	42"			for product	
					• •

Operator proposes to drill with air and air mist from under surface casing to 1200'

#### Projected tops:



Surface 8001 8901 1090' Maximum 12001


Mancos shale Dakota Sandstone Cedar Mountain Buckhorn ss

IN ABOVE SPACE DESCRIBE PROPOSED PROGRAM: If proposal is to deepen or plug back, give data on present productive zone and proposed new productive sone. If proposal is to drill or deepen directionally, give pertinent data on subsurface locations and measured and true vertical depths. Give blowout preventer program, 24. Feb. 4, 1975

Owner


CONDITIONS OF APPROVAL, IF ANY:

APPROVED BY



Section Corners (Brass Cap) Located

Well location as shown is in the NW 1/4, SE 1/4, Section 11, T218, R23E, S.L.B.M. Grand Cty, Utah



This is to certify that this plat was prepared from field notes of actual survey made Sept. 13, 1972 and that the same is true and correct to the best of my knowledge and belief.


Certified Profesational Geolog

ADAK ENERGY CORPORATION 68 South Main St.

Salt Lake City, Utah

Scale: 1" 1000"	Date Sept 19, 197.
Ref: GLO Plat	Approved

## T21S R23E S.L.B.M



Section Corners (Brass Cap) Located

Well location as shown is in the NE 4 NW 4 SE 4 Section 11, T21S, R23E S.L.B.M. Grand County, Utah



This to cartify that this plat was prepared aromafield notes of astual survey made June 20, 1872 and that the came is true and correct to best of my moviedge and belief.

Centines Problem sional Reployiet #13

ADAK ENERGY CORP.
38 South Main St.


Salt Lake City, Utah

Scale 1"=1000"

Date 111, 23, 1972

Ref: GLO Plat

oproved // 3-3-73



WELL LOCATION PLAT for Rig # 1

Broadhead Drilling Co.

Access road Trailers Rig Pog house Mud Pit Water Tank Ripe Rack Refuse Pit

February 5, 1975

Mr. Ed Guynn
Acting District Engineer,
U.S.G.S.
8th Floor Federal Bldg.
Salt Lake City, Utah 84111

Dear Sir:

Adak Energy Corp. would like to withdraw and cancel the application to drill on lease No. U 16965 in Section 11, T 21 S, R 23 E, Grand County, Utah which has been pending since September 8, 1962.

This acreage has been farmed out to C.C. Co. and a new application is herewith submitted to cover the proposed test in Section 11, T 21 S, R 23 E, Grand County, Utah.

Sincerely,

Lewis F. Wells

Agent

LFW/hw

#### February 13, 1975

C.C. Company 2723 Melbourne Street Salt Lake City, Utah 84106

> Re: Well No. Federal No. 11-1 Sec. 11, T. 21 S, R. 23 E, Grand County, Utah

#### Gentlemen:

Insofar as this office is concerned, approval to drill the above referred to well is hereby granted in accordance with the Order issued in Cause No. 102-5.

Should you determine that it will be necessary to plug and abandon this well, you are hereby requested to immediately notify the following:

CLEON B. FEIGHT - Director HOME: 466-4455 OFFICE: 328-5771

Enclosed please find Form OGC-8-X, which is to be completed whether or not water sands (aquifers) are encountered during drilling. Your cooperation relative to the above will be greatly appreciated.

The API number assigned to this well is 43-019-30230.

Very truly yours,

DIVISION OF OIL & GAS CONSERVATION

CLEON B. FEIGHT DIRECTOR

CBF:sw

cc: U.S. Geological Survey

7

### April 10, 1975

U.S.G.S., Oil & Gas Division 125 So. State Salt Lake City, Utah 84111

Attn: Mr. Ed Gwynn

Gentlemen:

Re: CC Co. test 11-1 Cisco, Grand Co., Utah Sec. 11, T 21 S, R 23 E API #43-019-30230

Please note corrected and revised location plat for CC Co. well, 11-1 to be drilled in Section 11, T 21 S, R 23 E in Grand County, Utah.

The revised copy is for your files and replaces the location plat filed with the original application.

Very Truly yours,

Lewis F. Wells CC Co., agent

LFW/hw

cc: R. Alexander
Dean H. Däristensen
Utah Oil & Gas Commission

ATTCHMENT 2-A SUMMAR" OF ENVIRONMENTAL IMPACT E"LUATION Adak Fed 11-1 Drilling Transport NWNE 11-215-23E Construction Cisco field Grund C. With U-16915 Pollution Production Operations Accidents Other

	USC-S-Alexanor BLM - Neggley CC - Lewis  10 Enhance  INO Effect  Mayor Impact	×	Transmission lines, pipelines	Dams & impoundments	Others (pump stations, compressor stations, etc.)	Burning, noise, junk disposal	arge	Subsurface disposal	Others (toxic gases, noxious gas, etc	Well drilling	Fluid removal (Prod. wells, facilities)	Secondary Recovery	Noise or obstruction of scenic views	processing (ext.	U Others	Trucks	Pipalines	Others	Spills and leaks	Operational failure	
	Forestry NA		1					, <u> </u>							_					:	
	Grazing	1		/		/															1
	Wilderness NA	-																			
	Agriculture NA	_										]									
	Residential-Commercial	H																			
30	Mineral Extraction NA	1/																			
٦ 9	Recreation L	- 0	<u>\</u>										4								-
puo.	Scenic Views L	1	1_										4								
	Parks, Reserves, Monuments WA				1									Ì		ļ					•
	Historical Sites N		+											7	_						
	Unique Physical Featurge	_	1											$\neg$	7						
_	Divdo	7	1									7	7		T						
& Fauna	Land Animals	1	<del>/                                    </del>								_	7	7	$\dashv$		$\supset$					
Fo	Fish N	<del>/</del>	╁	-		_					-			$\dashv$	+	<del>-</del>				<del></del>	
8	Endangered Species Kneu		┼									$\neg$	$\dashv$	$\dashv$	_		<del></del>				
Ö	Trees Cross Eds		1				7	$\neg$						$\dashv$	7					<del></del>	
-	Surface Water WA		+					ᅱ		•	_	_	-	1	1						
ဗ္ဗ	Underground Water 3		<del>                                     </del>					<del></del>			1	_	$\neg$	寸							<del> </del>
ğ	Air Quality	+	+					一		7	1	T		十	_	$\nearrow$					
S.	Erosion'		+					-1					7	1	+						
6	Surface Water WA- Underground Water ? Air Quality Erosion 2 Other	1	╁								<del>-</del>			十	$\dashv$						
-	Effect On Local Economy	+	†																		1-
		12		0														1			
_		1						_		0	_			-	_	0					
	Safety&Health					/					- [		$\lambda$	-							
	<u></u>	-				/															
	Others	1													T						<del></del>
		Ļ	1								[	.									
	CC. Qtbs, NRMA, Co RMCR. Pour Loab Comm, utin																				ENT 1
. ]	LOAG Comm, utin	-			1	ł	-	-	ı	- 1		1	-	-	]		1	- 1	1		C 111111111111111111111111111111111111

June 23, 1975

MEMO FOR FILING

Re: C.C. Company
Adak Lease 11-1
Cisco Field
Sec. 11, T. 21 S., R. 23 E.
Grand County, Utah

1) On June 23, 1975, at 8:30 a.m., after being notified by Cleon Feight that Dean Christensen had notified him of a blow-out on the above mentioned well, and that oil was escaping around the annular area between the surface casing and the surface hole.

Supposedly, 77' of surface pipe had been set and cemented to surface. (7" pipe in 9" hole) the T.D. at the time of the blow-out was 1123' K.B.

- 2) Called D. Christensen will be out of pocket until Wednesday.
- 3) Called U.S.G.S. talked with Bill Martin. He informed me that Ed Guinn had been there since Sunday. Well had been brought under control with heavy mud. The U.S.G.S. recommendations were not known at this time.
- 4) State Oil, Gas, and Mining Division passed on the following suggested recommendation to Bill Martin.
  - A) When well is under control and operator drills to permitted T.D., and when the  $4\frac{1}{2}$ " production casing is set, it be cemented from top to bottom by circulating cement to surface.

It appears, from third and fourth hand information, that when the well kicked, the B.O.P.'s were closed in, and excess pressure evidently ruptured the formation below the surface casing seat (inadequate amount of surface pipe) and allowed oil to leak around the outside of the surface pipe. There is no known reasonable way to secure this created condition without setting an intermediate string. The hole and casing program size virtually prohibits this,

Therefore, it is felt the recommendation to cement the production string from top to bottom, is the only safe and sure method.

The U.S.G.S. stated, that they would take this recommendation under advisement.

PATRICK L. DRISCOLL CHIEF PETROLEUM ENGINEER

PLD:tb

cc: U.S. GEOLOGICAL SURVEY

C.C. Company

#### June 26, 1975

#### MEMO FOR FILING

Re: C.C. Company
Adak Lease 11-1
Cisco Field

Sec. 11, T. 21 S., R. 23 E.

Grand County, Utah

Mr. Dean Christensen reported to this office the following information:

- 1) They were successful in controlling the well by circulating 16 #/gal drilling mud.
- 2) Approximately 300-400 BBLS of oil have been recovered from the mud pits.
- 3) Estimated daily flow rate is 250-300 BOPD.
- 4) The well will be logged approximately June 27, 1975, or as soon as surface clean-up work is completed.
- 5) The production casing will be cemented to the surface as previously suggested.

PATRICK L. DRISCOLL CHIEF PETROLEUM ENGINEER

#### PLD: tb

cc: U.S. GEOLOGICAL SURVEY

C.C. Company



# Unitable States Department of the Interior

GEOLOGICAL SURVEY Conservation Division 8426 Federal Building Salt Lake City, Utah 84138

June 30, 1975

Mr. Dean Christensen C. C. Company 2723 Melbourne Street Salt Lake City, Utah 84106

Re: Loss of Well Control
C. C. Co. Adak Well No. 11-1
NW\( \) SE\( \) Sec. 11-21S-23E
Grand County, Utah
Cisco Springs Field Area
Lease U-16965

Dear Mr. Christensen:

Your report of loss of well control on June 21, 1975, 4:30 p.m. for the referenced well is confirmed. BLM, Moab and EPA, Denver, have been notified. As a result of my onsite inspection of the well--control of the well had not been regained--June 23, 1975 12:30-4:00 p.m. This will also confirm oral requirements made at that time and in various telephone conversation with Mr. Lou Wells, consultant geologist. At the onsite inspection it was agreed that 200 bbls of 16-18 lb/gal mud would be necessary to regain control of the well. This volume and weight was mixed and pumped and well control was regained about 2:00 a.m. June 23, 1975. About 25 bbls of this volume of mud was not needed and was held in reserve. All oil from the well would be removed from the well site and the rig steam cleaned before starting engines and resuming operations with the rig. Oil production caught in the two retaining pits (one additional pit dug for that purpose to prevent entry of the oil into natural drainage) would be picked up and marketed. Approximately 185 bbls of oil have been trucked to market facilities to date. A June 24, 1975 telecon with Mr. Lou Wells indicated that the rig and location had been cleaned up and preparations were being made to resume operations. The drill pipe was stuck and could not be moved up or down. The following requirements were imposed on the resumption of operations:

1. A 2" line from the 2" access on the casing head under the BOP would be laid to the large pit (west of rig) and staked down. This line would be equipped with an adjustable choke or valve--preferably the choke--to facilitate future well control. (Completed)

- 2. A mud balance will be obtained for use at the rig. Mud weights will be checked frequently and entered in the Daily Drilling Log. Mud weight shall be maintained at a minimum of 16.0 lb/gal throughout the remainder of this operation.
- 3. When the pipe frees up and can be pulled out of the hole or it is decided to clean out to total depth, the hole shall be kept full at all times. Fill up will be made on the removal of each joint of drill pipe. (The rig pulls single joints.) Fill up is made with the kelly on and shall be checked with the pump shut down. The hole should be full and there should be no flow prior to pulling the next joint. In the event the decision is to clean out to Total Depth and condition the hole for logging, bottoms shall be circulated up on each joint drilled or washed down. These joints are about 25 ft. in length and extreme caution should be exercised in drilling down each joint. Prior to making connections the flow line shall be checked for flow--no flow of the mud column with pump off.
- 4. If the hole is logged, a lubricator capable of accepting the full length of the logging tool shall be rigged and pressure tested prior to the log run(s). A similar lubricator shall be rigged for any additional down hole wireline operations (perforating, etc.)
- 5. If production casing is run, it shall be cemented with a full column of cement to the surface or a minimum of 50 ft. into the surface casing (Minimum cement top at 47 ft.).
- 6. Daily reports of well activity and condition shall be made to this office--Phone 524-5650--or to my home if operations prohibit a call during office hours. My home phone is 582-7042 (Salt Lake)

Requirements Nos. 1 and 2 were reported as completed. Mud weight has been as low as 15.3 lb/gal. Some gas cutting is evident at this weight but this has been attributed to circulation rate. Mud weight should be maintained at minimum of 16.0 lb/gal.

This office recognizes that there have been many wells drilled in the Cisco Area without encountering abnormal pressures or loss of well control and that, in your well, this is probably a stray sand contribution to your loss of well control. All drilling operations in T21S, R23E, SLB&M Grand County, Utah, especially north of I-70 Freeway, have been or will be, on receipt of an Application for Permit to Drill, suspended until after a meeting in this office with the lessee or operator, drilling foreman or consultant in charge of the drilling operations, the contractor and other interested or involved party or parties, to discuss revision of casing programs and well control facilities. This does not include oper-

ations on Adak Well No. 11-1. These operations must continue diligently until the danger of loss of well control is passed—when the well is cased to total depth and completed or has been adequately cemented to the surface.

Sincerely yours,

E. W. Guynn

District Engineer

cc: A. A. Minerals, Salt Lake City
Lou Wells, Thompson Motel, Thompson, Utah
OGCC, Utah Attn: Mr. Pat Drescoll
O&GS, NRMA, Casper

USGS, Vernal

Form 9-331	U! STATES	SUBMIT IN TRII	,   <b>E</b>	Orm approved.
(May 1963) • DEPAR	MENT of THE INTER	CIOR (Other instruction.		Sudget Bureau No. 42-R1424. DESIGNATION AND SERIAL NO.
	GEOLOGICAL SURVEY			5965
	TICES AND REPORTS  cosals to drill or to deepen or plug CATION FOR PERMIT—" for such			AN, ALLOTTEE OR TRIBE NAME
OIL GAS WELL OTHER			7. UNIT AG	REEMENT NAME
2. NAME OF OPERATOR		11 - 21 - 21 - 21 - 21 - 21 - 21 - 21 -		R LEASE NAME
CCCO 3. ADDRESS OF OPERATOR			ADAK-	-CISCO
2723 Melbourne Street 4. Location of Well (Report location See also space 17 below.) At surface	Salt Lake City, Ut	ah 84106 y State requirements.*	11-1	GOVIT
1840' West of East Li T21S, R	ne, and 2160' N of S 23E Grand County, Uta		SUR	., R., M., OR BLK. AND VEY OR AREA  14 Sect 11
14. PERMIT NO.	15. ELEVATIONS (Show whether D	P PT CP etc.)	T21S.	
14. PERSIT NO.	4450 Gr	r, kt, GR, etc.)	Grand	
16. Charle A		N. CN. D	<del></del>	
	Appropriate Box To Indicate I	Nature of Notice, Kepo	-	
NOTICE OF INT	PULL OR ALTER CASING MULTIPLE COMPLETE	WATER SHUT-OFF	SUBSEQUENT REPORT	REPAIRING WELL ALTERING CASING
SHOOT OR ACIDIZE REPAIR WELL (Other)	ABANDON* CHANGE PLANS	SHOOTING OR ACIDIZ  (Other) (NOTE: Repor		ABANDONMENT*
proposed work. If well is direct nent to this work.)*  SEE ATTACHED SPECIAL I	tionally drilled, give subsurface local	ations and measured and tru	e vertical depths for	all markers and zones perti-
	•			
				. •
18. I hereby certify that the foregoing	/// Samuellande	General Manager	DAT	n _7/18/75
(/2.7/	Trules TITLE	General Manager	DAT	ø _7/18/75

(Rev. 5-68)	•	UNLEDS	STATES	SUBMIT	IN DUPLIC	othe in		approved. et Bureau No. 42-R355.5.
	DEPART						5. LEASE DESIGN	ATION AND SERIAL NO.
	GE	OLOGICAL	SURVEY	, 	•		U-16965	· · · · · · · · · · · · · · · · · · ·
	MPLETION C	R RECOM	PLETION, I	REPORT A	ND LO	G *	6. IF INDIAN, AL	LOTTEE OR TRIBE NAME
ia. TYPE OF WE	LL: OII, WELL	WELL X	DRY	Other			7. UNIT AGREEME	INT NAME
b. TYPE OF COM	WORK DEEP-	PLUG	DIFF. RESVR.	Other Cemer	ntad in	$\supset$ $\mid$	S. FARM OR LEAS	SE NAME
WELL	OVER L EN	☐ BACK ☐	RESVR.	Other Liemer	1000-111		VUVA CIC	co de la companya de
	Co						9. WELL NO.	,
3. ADDRESS OF OPE		CTDEET	CALTIANE	CITY UT	NIL 04106	.  -	11-1 GO	
4. LOCATION OF WE	723 MELBOURNE	SIKEEI  clearly and in acc	ORLI LAKE	y State requires	4H 84196 nents)*		Wildcat	
	O' West of E			V of S Lin	ne Sectio	on 11	. OR AREA	, OR BLOCK AND SURVEY
· At top prod. in	terval reported below	T21S, R2	3E		<b>†</b>	279		SECT 11
At total depth	•						-T21S R2	3E (8) - Sila
		ĺ	14. PERMIT NO.		TE ISSUED	·.	12. COUNTY OR PARISH	13. STATE
15. DATE SPUDDED	16. DATE T.D. REAC	HED   17. DATE C	43-019-30	<u> </u>	L MAY 75 ELEVATIONS (I	DE DE DE	GRAND	UTAH . ELEV. CASINGHEAD
	JUNE 21, 19		COMP.		4450 G		, dr. Elc.)	-0-
20. TOTAL DEPTH, MD	& TVD V 21. PLUG, F	BACK T.D., MD & TV		TIPLE COMPL.,	23. INT	ERVALS LLED BY	ROTARY TOOLS	CABLE TOOLS
1083'			UNKNO			<u>→</u>  S	urface to	25. WAS DIRECTIONAL
24. PRODUCING INTE	RVAL(S), OF THIS CO	MPLETION—TOP, B	OTTOM, NAME (:	MD AND IVD)*	V. 1			SURVEY MADE
<del>- 1055'-</del> 10	J62' CEDAR M	OUNTAIN ?_						NO.
26. TYPE ELECTRIC	AND OTHER LOGS RUN						27.	WAS WELL CORED
28.	ELECTRIC LO		RECORD (Rep	ort all strings	est in spell)			
CASING SIZE	WEIGHT, LB./FT.	DEPTH SET		LE SIZE		IENTING R	ECORD	AMOUNT PULLED
7"		971		8 3/4"	25	SXS		NONE
	CEE	CDECIAL D	CDODT I CT	TED				
	SEE.	SPECIAL R	EPUK LET	IEK				_
29.	LII	NER RECORD			30.	T	BING RECORD	
SIZE	<del> </del>	OTTOM (MD) SA	ACKS CEMENT*	SCREEN (MD)	SIZE	DI	EPTH SET (MD)	PACKER SET (MD)
	NONE							
31. PERFORATION RE	CORD (Interval, size	ind number)		32.	ACID, SHOT	, FRACTU	RE, CEMENT SQ	UEEZE, ETC.
	NONE			DEPTH INTE	RVAL (MD)	V 710	UNT AND KIND OF	MATERIAL USED
•	NONE			NONE	·	Ì	NONE	· · · · · · · · · · · · · · · · · · ·
				HOME	·····	<del></del>	HOME	
33.*  DATE FIRST PRODUCT	NON PRODUCT	ION METHOD (Flo			e specia		er report	US (Producing or
6/21/75		ELOUTHO .	UT OF CONT				shut-in)	<b>(</b>
DATE OF TEST	HOURS TESTED	CHOKE SIZE	PROD'N. FOR TEST PERIOD	OIL—BBL.	GAS-M	CF.	WATER-BBL.	GAS-OIL RATIO
6/21-22/75	36	-0-		193	<u> </u>		none	unknown
FLOW, TUBING PRESS.	-O-	CALCULATED 24-HOUR RATE	оц.—ввг. 360	GAS-M	cr.	WATER	1	gravity-api (corr.) nknown
34. DISPOSITION OF	AS (Sold, used for fue	l, vented, etc.)	2000				TEST WITNESSED	ву
	ENTED				****		USGS DIST	ENG. ED. GUYNN
35. LIST OF ATTACH		D LETTED O	M MELL					•
	CIAL ATTACHE			lete and correct	as determin	ed from al	l available record	is
SIGNED	ear J.C.	Sustan		ENERAL MA	NAGER		DAME 7	/18/75

#### SPECIAL REPORT ON CISCO, GRAND CO. WELL

C.C. Co. - Adak Gov't 11-1

This letter is to cover supporting data on the 11-1 test well, due to the circumstances associated with the drilling and subsequent blow out during the operation of this well.

On June 20th 1975, the operator cut an 8 foot porous sandstone at 1055' in the Cretaceous Cedar Mountain equivalent. This was oil stained and carried a good odor. Samples were circulated out and as this well was programed to test the Dakota and the two upper Morrison sandstones, the operator drilled one more joint (approximately 28') and circulated out, however, no show of gas or oil was evident in the mud and the hole was conditioned to run electric logs. A T.D. of 1083' was reaced at 11:30 a.m. June 21, 1975 and the driller circulated off bottom until Schlumberger arrived on location at 12:15. At that time they started out of the hole. The second joint of drill pipe pulled a little hard. All other conditions were normal. As the crew was breaking the 4th tool joint the well started to unload due to gas pressure. The driller put the kelly back on and contractor closed the blow out preventer (B.O.P.) which checked the flow.

In about two minutes a large surge of gas and oil erupted in the mud pit and blew mud and oil all over the rig area. The driller then backed off the B.O.P. and oil and gas started flowing around the drill pipe, striking the rig floor and by this time was out of control, either through and around the 7" surface pipe or belching and

discharging oil and gas in the mud pits. Flowing out of control continued for 38 hours, when it was killed at 2:05 a.m. June 23, 1975. The well flowed gas and oil at an estimated rate of 15 bbls. per hour of 360 bbls. per day.

Crews were put to work ditching trench and digging earth tanks all around the well site. 192 bbls. of brown crude were shipped from the reserve pit and the earthen pit which had been constructed to contain the oil on the east side of the location.

Two attempts to kill the well with heavy drilling mud were required to bring the well under control. On the first attempt 100 bbls of 14 pound Barite mud was pumped down the drill pipe but the gas and oil pressure blew this out as fast as the Fleet cementing truck could inject mud into the well bore. The next day, 200 bbls of 16 pound mud were mixed and after seven minutes the well was killed and under control.

Three days of clean up and getting the oil spill removed from the rig and around the adjacent area were required before starting up the drilling rig. On June 25 the mud pump was started, however operator could not break circulation and a Fleet mud pump was brought on location, The additional pumping equipment was needed as 1800 pounds of pumping pressure was required to break circulation after which driller circulated and maintained the same at 200 pounds. The driller then tried to pull drill pipe with up to 40,000 pounds pressure, the drill string weighing 12,000 pounds but the pipe held firm and every attempt and operating proceedure of pulling, jaring and rotating failed to free the string which was stuck at 107' off bottom.

On July 2, McCullough came on location, ran a free joint survey and found contact of the drill pipe at 737' and the nearest drill pipe tool joint at 714'. The operator then spotted 10 bbls of #2 diesel mixed with 10 gallons of Bariod Spot Free and let it sit for 12 hours. After numerous unsuccessful attempts to free the pipe, the decision to cement and abandon the well was made by the operator and approved by the U.S.G.S. District Engineer, Mr. Ed Gywnn of the Salt Lake office.

The operator then brought Fleet Cementers of Grand Junction back on location. They mixed 71 sacks of cement and pumped into the bore hole. McCullough then set a charge and the drill pipe was shot off at 714', leaving 3 joints of 2 7/8" drill pipe, 6 joints or 167' of 4" drill collars, a 2 foot sub and a 6 1/4" bit in the hole.

A second batch of cement was mixed and pumped into the hole. The balance of the 2 7/8" drill pipe was pulled as the cement level was raised in the hole and returns were circulated to surface. In all 197 sacks of cement were pumped into the hole and 32 joints (717 ft) of 2 7/8" drill pipe were recovered, leaving 89' of 2 7/8" drill pipe, 167' of drill collars and a 6 1/4" bit cemented in the hole.

The cementing operation was completed at 6:45 p.m. July 3, 1975 and an appropriate marker set at surface. A telephone report of plugging and cementing was made to the U.S.G.S. District Engineer's office at 7:30 p.m. and operations completed.


Dated: July 19, 1975

Second Thelle.

Geologist and Agent

WELL LOGGING REPORT





		Y-graphic								
DELLLING RATE IN MIN FT.	Depth	Inter 6		CAL CHARAC	TERISTS	RESER		REMARKS		
5 10 15 20 25	450		Rock Type & Color	Size & Shape	Asso. Minerals	Por. & Perm.	Oil or Gas Shows	Special Notes		
			Sh/silts	Verq	kd, dk gr	as		Ferron equi. v. hd. drilling		
			- "			/				
V			- "							
			- "							
	500		- "							
6-8	300		Sh, blk	to gray u	siltst.	lenses.				
		Section 1	- "	/ /						
	_	A COLUMN TO THE REAL PROPERTY OF THE PERSON	- 11							
			- "							
	550		" "							
	350	A MENT OF THE PARTY.	- Ir							
		MISS TO T	- 11							
			- "							
		Control of the Contro								
6-9-	600		- "							
			5il+st.	gray to	Itben.	tralau.		*		
6-10-6	40	- Continued		24						
			- sh/5//1	Ast be	Ntonitac.	white				
			- 1	1	ta- L.	- pasty.				
	650		- Shale	dk gray		/ /				
		Market I	"					1.46		
	=======================================	Property Co.	- "							
		The second second	-,					*		
		76 Stronger	*							
	700	Since The Control of	- "							
			- Shole.	It gray	pyritic	V. hd.				
6-11-7	20		Siltst	white	w/ cr, 9	L =.	3			
			"		/		1	Sty 743' 1st Show 3'APPRO		
			Ss. white	e-cl. f. g	Tr. Sub rd	clay filled	Live oil dk	10 Ter.		

	LITHOLOG	Y-graph	ic						
DRILLING RATE IN MIN/FT.	Depth	Inter		PHYSIC	CAL CHARAC	CTERISTS	RESE	RVIOR	REMARKS
5 10 15 20 25	750'			Rock Type & Color	Size & Shape	Asso.	Por. & Perm.	Oil or Gas Shows	Special Notes
6-17 766	<i>\$0</i> 0'			Ss. 9. Mudst - Sh Ss. Whi	te-cle Sh. qu	f-M Hd. 885' Cheri	w/banded  w/banded  w/banded  w/banded		Dakota, \$5.764'
6-/4 830	\$			Mudst Sh. Ls. Limy sh	Whi- gr	d Pink N Cast gray Mi	cro vlu		
6-15 830	850°			5,/757,	brn - wh,	lue gray ray sof MOTILE	<i>F. p</i> ,		
	900'			Mudst Shale Silst.	0-11	",			
F-17 950	950'			" Tr Mud st.	S. Vf.gr. blue-9	hd tot.	haly		
6 78 975	1000'			Sh Var Ss bra	rigated who che	975'. rtg V.hd.	tq†	Nove	CEDAR MTN Ss. 990' 2Nd LK sand equi drilled - 30' per foot.
				Sh. Silst Mudst. Sh.	Marron Marron	- bry ·	'+N		

BILLING RATE IN MIN / FT.	Depth	Y-graphic Inter 7	PHYSI	CAL CHARAC	TERISTS	RESE	RVIOR	REMARKS
5 10 15 20 25	1050'		Rock Typ= & Color	Size & Shape	Asso.	Por. & Perm.	Oil or Gas Shows	Special Notes
7. 8. E-21 10E3 12: 15 Pm.	83' <b>-</b>		SS. br Sh. w T.D. 10	brn - Mar.	firable - ted gtz gr.	Y Parous.	st. edor, t live oil stain	Puy Ss. 1055-63' & break 13-2's MIN per foot. 8'. No show of 95 IN & MIUD.  T.O. 1083'-
								This WELL blew out, when coming out of holetolog, 9 single stands - 107' off bottom. flowdoil + 995. estell bbls part for 38 his when operator killed
	1150							Well with. 16th mud. at, 2:0: AM, 6-23-15 and Shut in WELL, Operator could not pull. balance of drill pipe + colors, McCllough, shot of string at, 7:9- Operator, plugged, hole cotth 19:
								Prod - 1055-63, Flowed.  7-3-75  Prod - 1055-63, Flowed.  7as cut Oil 360 bbls prm.
								Perchy for 38 hrs; out of con 192 bbls of oil were ship from, reserve pit, Laation wo oil sat. for 100' around, well.
							2	

Form 9-331 (May 1963)	DEPAR'	UNTIED STA TMENT OF TH GEOLOGICAL	IE INTERIO	SUBMIT IN TRIE (Other instruction verse side)	18 On re-	Form app Budget B 5. LEASE DESIGNAT	ureau No. 42-R1424.
	this form for pro-	OTICES AND R	REPORTS C	ck to a different reserve		6. IF INDIAN, ALLO	TTEE OR TRIBE NAME
I.  OIL GAS WELL WEI	Γύlγ					7. UNIT AGREEMENT	F NAMB
	CH DRILLIN	G				8. FARM OR LEASE	MAMB
4. LOCATION OF WELL See also space 17	eway Place	, Suite 750 W	, San Jose	e, California State requirements.	95110	9. WHIL NO. VUKASOVIC	and the first transfer and all a very and the first transfer.
At Burfacé						Cisco Are 11. SEC., T., E., M., SURVEY OF A Sec 10, T2	N
14. PERMIT NO.		15. ELEVATIONS (	Show whether DF,	RT, GR, etc.)		12. COUNTY OR PAR GRAND	UTAH
The Well pipe into	NOTICE OF INT  DOCUMENTED ( If well is directly).  has 1032!  the zone.	PULL OR ALTER CAS' MULTIPLE COMPLETE ABANDON* CHANGE PLANS  DESCRIPTIONS (Clearly Stationally drilled, give)  of casin	ate all pertinent subsurface location	water shut-off fracture treatm shooting or acid (Other) (Note: Repo Completion of details, and give pertinous and measured and t	ENT IZING or Recomplet ent dates, in rue vertical	REPAIRII ALTERIN ABANDON f multiple completion Report and Log acluding estimated depths for all mar	on on Wall form.) date of starting any kers and sones perti-
A copy of subsequer	the cement of the temperature of the center	nt ticket from	n the serv	ice company wi	11 be p	resented wi	th the
• • • • • • • • • • • • • • • • • • •				DEGE NV. OF OIL, O			
	· · · · · · · · · · · · · · · · · · ·						

8. I her cerry that the foregoing is true and correct	TITLE ,_	AGENT			DATE 8	/29/83	
(This se for Federal or State office use)						Y De la Consti	
APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE		<del>12/</del>	· • · · · · · · · · · · · · · · · · · ·	DATE		